

# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones





Image and Object Parameters		Text Comments
Camera Model	FLIR FLIR T200_ Western	
Image Date	2009:10:06 12:36:29	
Image Name	Water leak behind stone work - Thermal.jpg	
Emissivity	0.93	
Reflected Temperature	20.0 °C	
Object Distance	3.5 m	

Description
moisture intrusion behind the brick work



# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones






Image and Object Parameters		Text Comments
Camera Model	FLIR FLIR T200_ Western	
Image Date	2009:05:27 13:19:23	
Image Name	basement wall - missing insulation thermal.jpg	
Emissivity	0.95	
Reflected Temperature	20.0 °C	
Object Distance	1.0 m	

Description
missing insulation behind the finished wall in the basement



# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones





Image and Object Parameters		Text Comments
Camera Model	FLIR FLIR T200_ Western	
Image Date	2009:09:01 13:38:50	
Image Name	ceiling moisture - thermal.jpg	
Emissivity	0.95	
Reflected Temperature	20.0 °C	
Object Distance	3.5 m	

Description
Moisture intrusion(dark area) that starts in middle of the kitchen area and goes to the east wall where the window is leaking



# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones





Image and Object Parameters		Text Comments
Camera Model	FLIR FLIR T200_ Western	
Image Date	2009:05:09 15:35:09	
Image Name	cold air intrusion under door-thermal.jpg	
Emissivity	0.95	
Reflected Temperature	20.0 °C	
Object Distance	1.0 m	

Description
darker area indicates there is moisture under the lino that appears to be coming from the bathroom area



# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones





Image and Object Parameters		Text Comments
<b>Camera Model</b>	FLIR FLIR T200_ Western	
<b>Image Date</b>	2009:07:17 20:44:09	
<b>Image Name</b>	how big is the damage - thermal.jpg	
<b>Emissivity</b>	0.93	
<b>Reflected Temperature</b>	20.0 °C	
<b>Object Distance</b>	5.0 m	

Description
Dark area shows how invovled the moisture is in the ceiling, that will need to be replaced to avoid mold growth



# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones





Image and Object Parameters		Text Comments
Camera Model	FLIR FLIR T200_ Western	
Image Date	2009:03:04 12:42:14	
Image Name	main Bathroom - thermal.jpg	
Emissivity	0.95	
Reflected Temperature	20.0 °C	
Object Distance	2.0 m	

Description
moisture intrusion from the ceiling/attic



# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones





Image and Object Parameters		Text Comments
Camera Model	FLIR FLIR T200_ Western	
Image Date	2000:01:01 00:26:49	
Image Name	in floor heating.jpg	
Emissivity	0.93	
Reflected Temperature	20.0 °C	
Object Distance	3.5 m	

**Description**  
in floor heating lines were located so further renovation can take place



# Inspection Report

**Report Date** 21/10/2009

**Company** Heat Seeker - Thermal Imaging  
**Address** 119 Kutz Cres, Saskatoon, Sk S7N 4S5  
**Thermographer** Clifford Gerow

**Customer** Paul Jones  
**Site Address** 218 Fun Street Saskatoon, Sk  
**Contact Person** Paul Jones




Image and Object Parameters		Text Comments
Camera Model	FLIR FLIR T200_ Western	
Image Date	2000:01:01 00:33:15	
Image Name	in floor heating lines.jpg	
Emissivity	0.93	
Reflected Temperature	20.0 °C	
Object Distance	3.5 m	

Description
hot water lines in the cement floor